

New concrete was installed outside the front door.

Emergency Exit signs are in place.

Bathrooms have painted floors, working exhaust fans, and functioning toilets and sinks. One bathroom has a nifty sliding barn door.

Vinyl plank flooring has been installed in the community room.

Painting is finished in two offices and the hallway.

A ramp leading up to the riser at the front of the sanctuary was designed and constructed.

The entry now sports a beautiful blue accent wall.